

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL043023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/20/2015
NAME OF PROVIDER OR SUPPLIER UNITED FAMILY CARE I		STREET ADDRESS, CITY, STATE, ZIP CODE 10183 HWY 210 N ANGIER, NC 27501		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 000	Initial Comments Report by Glenn Hoppin DHSR Construction Section conducted a Biennial Survey on November 20, 2015 from 2:30pm until 4:00 pm at the above referenced facility. DHSR records indicate the home was first licensed on February, 23 2010 as Family Care Home for six Residents ambulatory Residents (able to evacuate and respond without any physical or verbal assistance during a fire or other emergency) Based on this information, we are requiring the home to maintain compliance with the following; the 2005 Rules 10A NCAC 13G for Family Care Homes and the 2009 Edition of the North Carolina State Building Code - Section 421.2 - Residential Care Homes. At the time of our visit, we cited deficiencies that require an acceptable plan of correction. They are as follows:	C 000		
C 135	Bathroom-Hand Grips SECTION .0300 - THE BUILDING 10A NCAC 13G .0309 BATHROOM (e) Hand grips shall be installed at all commodes, tubs and showers used by the residents. This Rule is not met as evidenced by: Observations revealed that there are no grab bars on the toilet in the hall bath. Have a qualified technician install grab bars on the toilet. Provide photo documentation and receipts to the DHSR Construction Section.	C 135		
C 149	Outside Entrances/Exits-Handrails At Porches	C 149		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL043023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/20/2015
NAME OF PROVIDER OR SUPPLIER UNITED FAMILY CARE I		STREET ADDRESS, CITY, STATE, ZIP CODE 10183 HWY 210 N ANGIER, NC 27501		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 149	Continued From page 1 SECTION .0300 - THE BUILDING 10A NCAC 13G .0312 OUTSIDE ENTRANCE AND EXITS (f) All steps, porches, stoops and ramps shall be provided with handrails and guardrails. This Rule is not met as evidenced by: Observations revealed the porch in the car port does not have handrails. Have a qualified technician install handrails on the porch. Provide photo documentation and receipts to the DHSR Construction Section.	C 149		
C 174	Building Equipment Maintained Safe, Operating SECTION .0300 - THE BUILDING 10A NCAC 13G .0317 BUILDING SERVICE EQUIPMENT (a) The building and all fire safety, electrical, mechanical, and plumbing equipment in a family care home shall be maintained in a safe and operating condition. (j) This Rule shall apply to new and existing family care homes. This Rule is not met as evidenced by: 1. Observations revealed that the handicap ramp is rotted and in a state of disrepair. Have a qualified technician make all necessary repairs. Provide photo documentation and all receipts to the DHSR Construction Section. 2. Observations revealed the required inside handrail on the rear handicap ramp is missing. Have a qualified technician install a handrail on the inside of the handicap ramp. Provide photo documentation to the DHSR Construction Section.	C 174		

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: FCL043023	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 B. WING _____	(X3) DATE SURVEY COMPLETED 11/20/2015
NAME OF PROVIDER OR SUPPLIER UNITED FAMILY CARE I		STREET ADDRESS, CITY, STATE, ZIP CODE 10183 HWY 210 N ANGIER, NC 27501		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
C 174	Continued From page 2 3. Observations revealed that the Dryer is exhausting to the crawl space. Have a qualified technician install metal duct work to vent the dryer to the exterior of the facility. Provide photo documentation and receipts to the DHSR Construction section.	C 174		